



Waimanalo Gulch Landfill

*92-460 Farrington Highway,
Kapolei, HI*



Photos assembled by
Steve Tyahla, P.E., CHMM
EPA 9, RCRA Corrective Action Office
(415) 972-3466 / tyahla.stephen@epa.gov









2008 Image

Image USGS
© 2010 Google

© 2010 Google™



2008 Image

Image USGS

© 2010 Google

© 2010 Google™



Image USGS
© 2010 Google


2008 Image
© 2010 Google™



04 Jan 2011



04 Jan 2011



“Up canyon” temporary berm and drain



04 Jan 2011





04 Jan 2011





04 Jan 2011



04 Jan 2011



04 Jan 2011



13 Jan 2011





13 Jan 2011



13 Jan 2011



13 Jan 2011



13 Jan 2011





13 Jan 2011



13 Jan 2011



13 Jan 2011



13 Jan 2011



14 Jan 2011



14 Jan 2011



14 Jan 2011

Video Pan of Outfalls taken by ST on 18 Jan 2011
to show scale of outfalls



Sat., 15 Jan 2011



Sat., 15 Jan 2011



Sat., 15 Jan 2011



Sat., 15 Jan 2011



Sat., 15 Jan 2011



Sat., 15 Jan 2011





Sun., 16 Jan 2011



Sun., 16 Jan 2011



Sun., 16 Jan 2011



Sun., 16 Jan 2011



Sun., 16 Jan 2011



Sun., 16 Jan 2011



Sun., 16 Jan 2011



Wed., 19 Jan 2011



Wed., 19 Jan 2011



Wed., 19 Jan 2011



Wed., 19 Jan 2011



Wed., 19 Jan 2011



Wed., 19 Jan 2011



Wed ,19 Jan 2011



Wed., 19 Jan 2011



Wed., 19 Jan 2011



Sun., 16 Jan 2011





04 Jan 2011



13 Jan 2011



Sun., 16 Jan 2011



Wed., 19 Jan 2011



04 Jan 2011



13 Jan 2011



Wed., 19 Jan 2011



Wed., 19 Jan 2011



Tue., 18 Jan 2011



Tue., 18 Jan 2011



Tue., 18 Jan 2011



Tue., 18 Jan 2011



Tue., 18 Jan 2011